



Steel Flange Reinforcing Joint Repair Joint for Flange

RJF



We can also offer solutions for high pressure and fluids other than water, depending on the situation.



Material: SS400, SUS304
Size: 3"/DN80 ~ 80"/DN2000
Rubber ring: SBR, EPDM, Silicon etc.

Features

Leakage due to corrosion or opening of the flange can be repaired without cutting off the water supply. Custom-made to match the existing flange, so it can be adapted to any situation. Rubber ring with automatic sealing mechanism is used to achieve continuous water sealing performance.

Installation Process



1 Pre-measurement



2 Replacement of flange bolts



3 Surface preparation & painting



4 Rubber ring installed



5 Completed

Contact

+81-52-223-8251

hirano@victaulic.co.jp

<https://victaulic.co.jp>

460-0002
Metlife Nagoya Marunouchi building, 2-20-25,
Marunouchi, Naka-ku, Nagoya-shi, Aichi, Japan

